



- Subject** ▶ Elimination of Rubber Pin 4,
Change of Gear Cover Complete
- For Models** ▶ 9401, 9402
- Country** ▶ All countries
- Description** ▶ Rubber pin 4 has been eliminated from Gear cover complete.

▶ Current	▶ New
<p>Gear Cover Complete (152204-1) comes with rubber pin 4 (263002-9).</p>  <p>Installation hole (Rubber pin 4)</p>	<p>Gear Cover (312549-1)</p>  <p>Installation hole and Rubber pin 4 have been eliminated.</p>

Interchangeability(I/C)

Item No.	Current part		Q'ty	I/C	New part		Q'ty	Note
9401: 065 9402: 069	Gear Cover Complete 152204-1		1	Yes	Gear Cover 312549-1		1	
9401: 064 9402: 073	Rubber Pin 4 263002-9		1					

Implementation

To be implemented from March, 2005 production.